

SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING

Site: Education Center

8-Aug-17

Sampler SDUSD-Safety Office

Analyzed by: Enviromatrix Labs 17G0821 Ed Center

Sample ID	Sample Date	Sample Location	Lead result	Units	Type of Fixture
1	27-Jul	Main Bldg- 1st floor C Wing	18	ug/l	drinking fountain
2	27-Jul	Main Bldg- 1st floor B Wing	11	ug/l	rightside drinking fountain
3	27-Jul	Main Bldg- 1st floor B Wing west	9	ug/l	drinking fountain
4	27-Jul	Main Bldg- 1st floor A Wing	10	ug/l	leftside drinking fountain
5	27-Jul	Main Bldg- 2nd floor A Wing north	9	ug/l	drinking fountain
6	27-Jul	Main Bldg- 2nd floor B Wing west	10	ug/l	drinking fountain
7	27-Jul	Main Bldg- 2nd floor B Wing southwest	10	ug/l	drinking fountain
8	27-Jul	Main Bldg- 3rd floor B Wing southwest	6	ug/l	drinking fountain
9	27-Jul	Main Bldg- 3rd floor A Wing north	ND	ug/l	drinking fountain
10	27-Jul	Main Bldg- 3rd floor A Wing	7	ug/l	drinking fountain

SAN DIEGO UNIFIED SCHOOL DISTRICT DRINKING WATER SAMPLING

Site: Education Center

8-Aug-17

Sampler SDUSD-Safety Office

Analyzed by: Enviromatrix Labs 17G0821 Ed Center

Sample ID	Sample Date	Sample Location	Lead result	Units	Type of Fixture
11	27-Jul	Annex 8 Sandi Café	ND	ug/l	sink faucet
12	27-Jul	Annex 2 West Entry North	12	ug/l	drinking fountain
13	27-Jul	Annex 17 Break Room	ND	ug/l	sink faucet
14	27-Jul	School Police- Break Room	ND	ug/l	sink faucet
15	27-Jul	Annex 5 Break Room	25	ug/l	sink faucet