



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309


Water Quality Chemistry Services
Lead School Testing
Report Date: 3/14/19

San Diego Unified School District
Magnolia Science Academy

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1285385	01/25/19	06:40 AM	SAMPLE 1	3710020-CHC-A	< 5	ug/L
W1285386	01/25/19	06:42 AM	SAMPLE 2	3710020-CHC-B	< 5	ug/L
W1285387	01/25/19	06:35 AM	SAMPLE 3	3710020-CHC-C	< 5	ug/L
W1285388	01/25/19	06:37 AM	SAMPLE 4	3710020-CHC-D	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Girls restroom building, North facing wall, double bubbler, lower left bubbler
SAMPLE 2	Girls restroom building, North facing wall, double bubbler, upper right bubbler
SAMPLE 3	MPR, South Facing Wall, double wall mount fountain, upper right bubbler
SAMPLE 4	MPR, South Facing Wall, double wall mount fountain, lower left bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist