



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/27/17

San Diego Unified School District
Adams Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1166836	04/15/17	08:24 AM	SAMPLE 1	3710020-AFD-A	< 5	ug/L
W1166837	04/15/17	08:27 AM	SAMPLE 2	3710020-AFD-B	< 5	ug/L
W1166838	04/15/17	08:30 AM	SAMPLE 3	3710020-AFD-C	< 5	ug/L
W1166839	04/15/17	08:33 AM	SAMPLE 4	3710020-AFD-D	< 5	ug/L
W1166840	04/15/17	08:36 AM	SAMPLE 5	3710020-AFD-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 BLDG 200, prep kitchen near entrance, swing arm faucet
- SAMPLE 2 BLDG 300, 1st floor, near room 1 and science lab, lower left bubbler
- SAMPLE 3 BLDG 300, 1st floor, between gardner and D3 rooms, triple fountain, left bubbler
- SAMPLE 4 BLDG 300, 1st floor, west end, between kindergarten rooms 5 & 6, triple fountain, left bubbler
- SAMPLE 5 BLDG 300, room 14, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist