



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/23/17

San Diego Unified School District  
**Alcott Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1170038	05/10/17	06:11 AM	SAMPLE 1	3710020-BEI-A	< 5	ug/L
W1170039	05/10/17	06:09 AM	SAMPLE 2	3710020-BEI-B	< 5	ug/L
W1170040	05/10/17	06:02 AM	SAMPLE 3	3710020-BEI-C	< 5	ug/L
W1170041	05/10/17	06:00 AM	SAMPLE 4	3710020-BEI-D	< 5	ug/L
W1170042	05/10/17	05:59 AM	SAMPLE 5	3710020-BEI-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1      Kindergarten Area, North side of campus outside between Rooms 3 and 4, Sink with Faucet and a bubbler, bubbler is on right
- SAMPLE 2      Building on Northwest side of campus near blacktop near rooms 20 and 21, triple bubbler fountain, center bubbler
- SAMPLE 3      Center of campus on West facing wall near room 17 & RRs, triple bubbler fountain, left bubbler
- SAMPLE 4      South side of campus inside Room 15, bubbler at sink
- SAMPLE 5      South side of campus inside Room 14, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist