



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/9/17

San Diego Unified School District
Bandini Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1165211	05/02/17	05:48 AM	SAMPLE 1	3710020-ACH-A	< 5	ug/L
W1165212	05/02/17	05:51 AM	SAMPLE 2	3710020-ACH-B	< 5	ug/L
W1165213	05/02/17	06:00 AM	SAMPLE 3	3710020-ACH-C	< 5	ug/L
W1165214	05/02/17	05:56 AM	SAMPLE 4	3710020-ACH-D	< 5	ug/L
W1165215	05/02/17	06:05 AM	SAMPLE 5	3710020-ACH-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Admin BLDG, west wall near corner, triple fountain, right bubbler
SAMPLE 2	Kitchen, outside kitchen service building, double fountain, right bubbler
SAMPLE 3	BLDG 7,8,9, near room 9, around corner from restrooms, double fountain, right bubbler
SAMPLE 4	BLDG 7,8,9, in room 9, bubbler at sink
SAMPLE 5	BLDG 10,11,12,13 in room 11, left side, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist