



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/12/17

San Diego Unified School District  
**Burbank Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168067	05/03/17	06:07 AM	SAMPLE 1	3710020-BAA-A	< 5	ug/L
W1168068	05/03/17	06:19 AM	SAMPLE 2	3710020-BAA-B	< 5	ug/L
W1168069	05/03/17	05:56 AM	SAMPLE 3	3710020-BAA-C	< 5	ug/L
W1168070	05/03/17	06:02 AM	SAMPLE 4	3710020-BAA-D	< 5	ug/L
W1168071	05/03/17	05:59 AM	SAMPLE 5	3710020-BAA-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    Building 200 (first floor), Outside drinking fountain next to BDF/IDF/ Girls Bathroom(Hall way), two single bubbler fountains, lower right fountain
- SAMPLE 2    Building 200 (Second Floor), Outside drinking fountain next to electrical room, two single bubbler fountains, lower right fountain
- SAMPLE 3    Building 300, Outside drinking fountain next to the 300 building south entrance, two single bubbler fountains, upper left fountain
- SAMPLE 4    Outside building 100 (playground), Drinking fountain in front of Building, two single bubbler fountains, upper left fountain
- SAMPLE 5    inside Building 300 (Kitchen), faucet above single basin sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Tom Burger, Associate Chemist