



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/17/17

San Diego Unified School District  
**Carson Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168191	04/22/17	07:41 AM	SAMPLE 1	3710020-AJI-A	< 5	ug/L
W1168192	04/22/17	07:43 AM	SAMPLE 2	3710020-AJI-B	< 5	ug/L
W1168193	04/22/17	07:46 AM	SAMPLE 3	3710020-AJI-C	< 5	ug/L
W1168194	04/22/17	07:50 AM	SAMPLE 4	3710020-AJI-D	< 5	ug/L
W1168195	04/22/17	07:53 AM	SAMPLE 5	3710020-AJI-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Room 14 exterior east wall, triple fountain, left bubbler
SAMPLE 2	South/East facing wall at playground, next to girls RR, triple fountain, center bubbler
SAMPLE 3	Kindergarten playground , next to RM36, left bubbler on dual white fountain
SAMPLE 4	Cafeteria, kitchen south wall, spray nozzle
SAMPLE 5	South facing wall near boys RR, triple fountain, center bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist