



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/17/17

San Diego Unified School District
Chesterton Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168171	04/22/17	08:09 AM	SAMPLE 1	3710020-AJE-A	5.02	ug/L
W1168172	04/22/17	08:10 AM	SAMPLE 2	3710020-AJE-B	5.29	ug/L
W1168173	04/22/17	08:15 AM	SAMPLE 3	3710020-AJE-C	< 5	ug/L
W1168174	04/22/17	08:23 AM	SAMPLE 4	3710020-AJE-D	< 5	ug/L
W1168175	04/22/17	08:18 AM	SAMPLE 5	3710020-AJE-E	< 5	ug/L

Source	Source Description
SAMPLE 1	Auditorium exterior, North east corner, lower left bubbler
SAMPLE 2	Kitchen, south wall, right of range, wall mount faucet
SAMPLE 3	BLDG 200, south exterior facing blacktop, triple fountain, right bubbler
SAMPLE 4	BLDG 300, east exterior next to girls RR, triple white fountain, center bubbler
SAMPLE 5	B-50 classroom, bubbler at sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist