



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/12/17

San Diego Unified School District
Clark Middle

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168057	05/02/17	05:57 AM	SAMPLE 1	3710020-AJD-A	< 5	ug/L
W1171700	05/06/17	07:51 AM	SAMPLE 2	3710020-AJD-B	< 5	ug/L
W1168059	05/02/17	06:17 AM	SAMPLE 3	3710020-AJD-C	< 5	ug/L
W1171699	05/06/17	07:48 AM	SAMPLE 4	3710020-AJD-D	< 5	ug/L
W1168061	05/02/17	06:13 AM	SAMPLE 5	3710020-AJD-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Kitchen, West side of kitchen near service area, sink faucet in wash sink, sign: "washing sink for fruits and vegetables only"
SAMPLE 2	Main Building, westside of campus, north of library, under stairs near parent center, upper right bubbler
SAMPLE 3	400 / P.E. Building, Exterior drinking fountain on south wall adjacent to racquetball courts, two single bubbler fountains, upper right fountain
SAMPLE 4	200 bldg, 1st floor, northend between RMs 208-208, 2 single buublers, lower left bubbler
SAMPLE 5	200 Buildiing, room 207, sink faucet in center of room

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist