



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/27/17

San Diego Unified School District
Clay Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1166678	04/14/17	06:01 AM	SAMPLE 1	3710020-AFA-A	< 5	ug/L
W1166679	04/14/17	06:04 AM	SAMPLE 2	3710020-AFA-B	< 5	ug/L
W1166680	04/14/17	06:09 AM	SAMPLE 3	3710020-AFA-C	< 5	ug/L
W1166681	04/14/17	06:18 AM	SAMPLE 4	3710020-AFA-D	< 5	ug/L
W1166682	04/14/17	06:14 AM	SAMPLE 5	3710020-AFA-E	10.5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Kindergarten building, Exterior east facing wall near gate, small fountain w/single bubbler
SAMPLE 2	Nurses office, bubbler at sink
SAMPLE 3	Main BLDG, near room 2, triple fountain, right bubbler
SAMPLE 4	West facing wall near room 10, triple fountain, center bubbler
SAMPLE 5	Cafeteria bldg, south wall, two fountains, lower right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist