



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/23/17

San Diego Unified School District
Crown Point Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1171679	05/11/17	06:09 AM	SAMPLE 1	3710020-BGG-A	< 5	ug/L
W1171680	05/11/17	06:15 AM	SAMPLE 2	3710020-BGG-B	< 5	ug/L
W1171681	05/11/17	06:18 AM	SAMPLE 3	3710020-BGG-C	< 5	ug/L
W1171682	05/11/17	06:21 AM	SAMPLE 4	3710020-BGG-D	< 5	ug/L
W1171683	05/11/17	06:25 AM	SAMPLE 5	3710020-BGG-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Kitchen, Inside kitchen at food prep sink below window, faucet at 2 compartment sink
- SAMPLE 2 4-14 bldg, Outside between RRs and #10, dual bubbler fountain left of single fountain, left bubbler on dual fountain
- SAMPLE 3 Outside K-1 bldg, north wall at black top playground, two single bubbler fountains, lower right fountain
- SAMPLE 4 K-1 bldg, South wall near kinder playground, single bubbler fountain
- SAMPLE 5 16-18 bldg, Outside Between boys & girls RRs, triple bubbler fountain, middle bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist