



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/23/17

San Diego Unified School District  
**Doyle Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1171640	05/09/17	06:00 AM	SAMPLE 1	3710020-BGD-A	< 5	ug/L
W1171641	05/09/17	06:00 AM	SAMPLE 2	3710020-BGD-B	< 5	ug/L
W1171642	05/09/17	06:05 AM	SAMPLE 3	3710020-BGD-C	< 5	ug/L
W1171643	05/09/17	06:05 AM	SAMPLE 4	3710020-BGD-D	< 5	ug/L
W1171644	05/09/17	06:15 AM	SAMPLE 5	3710020-BGD-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Admin Building, South side of Admin. near RRs, two single bubbler fountains, upper right fountain
SAMPLE 2	300 Building, West side of building near RRs, triple bubbler fountain, right bubbler
SAMPLE 3	400 Building, West side of bldg near RRs, triple bubbler fountain, right bubbler
SAMPLE 4	500 Building, South side of building, triple bubbler fountain, right bubbler
SAMPLE 5	Café Building (Kitchen), south side of Auditorium, faucet above two-compartment sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist