



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/5/17

San Diego Unified School District
East Village High

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168627	04/28/17	05:50 AM	SAMPLE 1	3710020-BGB-A	< 5	ug/L
W1168628	04/28/17	05:55 AM	SAMPLE 2	3710020-BGB-B	< 5	ug/L
W1168629	04/28/17	06:00 AM	SAMPLE 3	3710020-BGB-C	< 5	ug/L
W1168630	04/28/17	06:02 AM	SAMPLE 4	3710020-BGB-D	< 5	ug/L
W1168631	04/28/17	06:05 AM	SAMPLE 5	3710020-BGB-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	East interior wall of staff break room, bubbler at sink
SAMPLE 2	Room B-2, art room, bubbler at sink
SAMPLE 3	Room B-3, Island at front of room, bubbler at sink
SAMPLE 4	Room B-2, south interior wall, bubbler at sink
SAMPLE 5	East side of campus, next to fence, pedestal, lower bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist