



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/12/17

San Diego Unified School District
Farb Middle

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1169429	05/06/17	06:40 AM	SAMPLE 1	3710020-BEG-A	< 5	ug/L
W1169430	05/06/17	06:47 AM	SAMPLE 2	3710020-BEG-B	< 5	ug/L
W1169431	05/06/17	06:49 AM	SAMPLE 3	3710020-BEG-C	< 5	ug/L
W1169432	05/06/17	06:43 AM	SAMPLE 4	3710020-BEG-D	< 5	ug/L
W1169433	05/06/17	06:53 AM	SAMPLE 5	3710020-BEG-E	6.97	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Cafeteria Bldg, Outside West facing wall next to Cafeteria, triple bubbler fountain, middle bubbler
SAMPLE 2	Bldg Rooms 50-56, West facing wall next to Room 51, triple bubbler fountain, right bubbler
SAMPLE 3	Bldg Rooms 41-46, West facing wall next to Room 41, triple bubbler fountain, left bubbler
SAMPLE 4	Kitchen, spray nozzle over right sink compartment
SAMPLE 5	Administration/Main Office Bldg, Interior fountain center of office, two single-bubbler fountains, lower left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist