



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/9/17

San Diego Unified School District
Fay Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1166936	05/02/17	05:58 AM	SAMPLE 1	3710020-AFF-A	< 5	ug/L
W1166937	05/02/17	06:12 AM	SAMPLE 2	3710020-AFF-B	< 5	ug/L
W1166938	05/02/17	06:00 AM	SAMPLE 3	3710020-AFF-C	< 5	ug/L
W1166939	05/02/17	06:05 AM	SAMPLE 4	3710020-AFF-D	< 5	ug/L
W1166940	05/02/17	06:07 AM	SAMPLE 5	3710020-AFF-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Main building, near elevator mechanical, upper right bubbler
SAMPLE 2	Main bldg, 2nd floor near custodial storage, lower left
SAMPLE 3	Kindergarten bldg, exterior north wall, upper right bubbler
SAMPLE 4	Cafeteria, exterior south wall between boys/girls RR, lower right bubbler
SAMPLE 5	Kitchen single compartment sink to the right of 3 stage sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist