



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/23/17


San Diego Unified School District
Fletcher Elementary

| Sample ID | Sample Date | Sample Time | Source | External ID | Lead | Units |
|-----------|-------------|-------------|----------|---------------|------|-------|
| W1168612 | 05/09/17 | 05:57 AM | SAMPLE 1 | 3710020-BCC-A | < 5 | ug/L |
| W1168613 | 05/09/17 | 06:01 AM | SAMPLE 2 | 3710020-BCC-B | 6.82 | ug/L |
| W1168614 | 05/09/17 | 05:52 AM | SAMPLE 3 | 3710020-BCC-C | < 5 | ug/L |
| W1168615 | 05/09/17 | 06:08 AM | SAMPLE 4 | 3710020-BCC-D | < 5 | ug/L |
| W1168616 | 05/09/17 | 06:11 AM | SAMPLE 5 | 3710020-BCC-E | < 5 | ug/L |

Source **Source Description**

- SAMPLE 1 Classrooms 1-6 bldg, South exterior end of building near basketball court, two single bubbler fountains, upper left fountain
- SAMPLE 2 Classrooms 7-12 bldg, South end of building near black top play area, triple bubbler fountain, left bubbler
- SAMPLE 3 Cafeteria, Outside next to lunch court, two single bubbler fountain, lower left fountain
- SAMPLE 4 Kindergarten Bldg, Inside K-1, bubbler on right side of sink with double faucets
- SAMPLE 5 Kindergarten Bldg, Inside K-2, bubbler on right side of sink with double faucets

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist