



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/12/17

San Diego Unified School District
Garfield Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168297	05/03/17	06:02 AM	SAMPLE 1	3710020-BAD-A	< 5	ug/L
W1168298	05/03/17	06:04 AM	SAMPLE 2	3710020-BAD-B	< 5	ug/L
W1168299	05/03/17	06:07 AM	SAMPLE 3	3710020-BAD-C	< 5	ug/L
W1168300	05/03/17	06:15 AM	SAMPLE 4	3710020-BAD-D	5.26	ug/L
W1168301	05/03/17	06:13 AM	SAMPLE 5	3710020-BAD-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 MultiPurpose Room (MPR)/Kitchen, Wall mounted along the hallway, between Girls & Boys RR, facing Classroom 9, dual bubbler fountain, right bubbler
- SAMPLE 2 Kitchen, Wall mounted exterior (South of Bldg), between Kitchen & Rm 10, facing Lunch Court, dual bubbler fountain, left bubbler
- SAMPLE 3 Blg w/ Classrooms 12-18, Wall mounted exterior (East of Bldg), between Classrooms 17 & 16, facing playground/blacktop, dual bubbler fountain, left bubbler
- SAMPLE 4 classroom 2, classroom sink/faucet, bubbler with push button cap at sink
- SAMPLE 5 CDC, CC3, classroom sink/faucet, 2 sinks, bubbler on right sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist