

Water Quality Chemistry Services
 Lead School Testing
 Report Date: 28-Apr-2017


San Diego Unified School District
Garfield High School

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1167057	4/18/2017	5:59 AM	SAMPLE 1	3710020-AGG-A	< 5	µg/L
W1167058	4/18/2017	6:03 AM	SAMPLE 2	3710020-AGG-B	< 5	µg/L
W1167059	4/18/2017	6:09 AM	SAMPLE 3	3710020-AGG-C	< 5	µg/L
W1167060	4/18/2017	6:13 AM	SAMPLE 4	3710020-AGG-D	< 5	µg/L
W1167061	4/18/2017	6:16 AM	SAMPLE 5	3710020-AGG-E	< 5	µg/L

Source **Source Description**

- SAMPLE 1 East Wing; near ASB; 1st floor east wall between men and women's RR; Lower Left Bubbler next to Men's RR
- SAMPLE 2 Culinary Arts Kitchen; Right sink faucet
- SAMPLE 3 West Wing; Fourth floor exterior west wall next to elevator; Left bubbler
- SAMPLE 4 West Wing; 3rd floor exterior west wall across from women's restroom; Upper Left bubbler
- SAMPLE 5 West Wing; 2nd floor exterior west wall next to men's restroom; Lower Right bubbler

DRL=State Mandated Detection Limit for Reporting (DLR)= 5 µg/L
 Action Level (AL) = 15 µg/L


 Doug Campbell, Senior Chemist