



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/4/17

San Diego Unified School District
Harriet Tubman Charter

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168343	04/26/17	06:15 AM	SAMPLE 1	3710020-BAE-A	< 5	ug/L
W1168344	04/26/17	06:12 AM	SAMPLE 2	3710020-BAE-B	< 5	ug/L
W1168345	04/26/17	06:09 AM	SAMPLE 3	3710020-BAE-C	9.84	ug/L
W1168346	04/26/17	06:27 AM	SAMPLE 4	3710020-BAE-D	< 5	ug/L
W1168347	04/26/17	06:20 AM	SAMPLE 5	3710020-BAE-E	< 5	ug/L

Source

Source Description

- SAMPLE 1 Main (Admin) Building, Outside (NW corner) of main building on West facing wall, triple bubbler fountain, middle bubbler
- SAMPLE 2 Cafeteria Building, Outside wall facing North, two sets of two single bubbler fountains, right set of fountains, lower left fountain
- SAMPLE 3 Inside Kitchen far South wall, regular faucet (not pull down) on 3 compartment sink
- SAMPLE 4 Kindergarten Building, Room K-1, Single Bubbler on sink
- SAMPLE 5 Bungalow Building, Outside of Room 16, freestanding fixture with 2 single bubbler fountains, lower fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist