



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/12/17
San Diego Unified School District
Johnson Elementary School

Sample ID	Sample Date	Sample Time	Description	External ID	Lead	Units
W1164268	04/05/17	05:50 AM	SAMPLE 1	3710020-ABH-A	< 5	ug/L
W1164269	04/05/17	05:55 AM	SAMPLE 2	3710020-ABH-B	< 5	ug/L
W1164270	04/05/17	06:00 AM	SAMPLE 3	3710020-ABH-C	< 5	ug/L
W1164271	04/05/17	06:10 AM	SAMPLE 4	3710020-ABH-D	< 5	ug/L
W1164272	04/05/17	06:15 AM	SAMPLE 5	3710020-ABH-E	< 5	ug/L

Sample Site

- SAMPLE 1 Kindergarten; S. wall Btwn Rm K1 & Storage RM 1. Right bubbler
- SAMPLE 2 Cafeteria; E. wall @ Lunch Court; Upper/Left Bubbler
- SAMPLE 3 Rm 1-6; S. wall btwn girls restroom & RM 4; right bubbler
- SAMPLE 4 Child Development Cntr. S/E corner; E. wall playground; left bubbler
- SAMPLE 5 Staff/Student portable restrooms/ btwn men&women's restroom. Lower/right bubbler

DLR= State Mandated Detection Limit for Reporting (DLF
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist