



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/23/17

San Diego Unified School District
Kearny SCT

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1171684	05/12/17	06:05 AM	SAMPLE 1	3710020-BHE-A	< 5	ug/L
W1171685	05/12/17	06:00 AM	SAMPLE 2	3710020-BHE-B	< 5	ug/L
W1171686	05/12/17	06:15 AM	SAMPLE 3	3710020-BHE-C	< 5	ug/L
W1171687	05/12/17	06:08 AM	SAMPLE 4	3710020-BHE-D	< 5	ug/L
W1171688	05/12/17	05:58 AM	SAMPLE 5	3710020-BHE-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Cafeteria, West Interior Wall, Single Faucet above single compartment sinks
- SAMPLE 2 Lunch Court, East Facing Wall, two single bubbler fountains, upper right fountain
- SAMPLE 3 Boys Locker Room, East Facing Exterior Wall, triple bubbler fountain, right bubbler
- SAMPLE 4 Girls Gym, South Exterior Wall, triple bubbler fountain, left bubbler
- SAMPLE 5 Auditorium, Interior wall mounted, left side as you enter building, two single bubbler fountains, lower left fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist