



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/23/17

San Diego Unified School District
King-Chavez Academy

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168358	04/27/17	06:00 AM	SAMPLE 1	3710020-BBC-A	< 5	ug/L
W1168359	04/27/17	06:02 AM	SAMPLE 2	3710020-BBC-B	< 5	ug/L
W1168360	04/27/17	06:05 AM	SAMPLE 3	3710020-BBC-C	< 5	ug/L
W1168361	04/27/17	06:10 AM	SAMPLE 4	3710020-BBC-D	< 5	ug/L
W1168362	04/27/17	06:12 AM	SAMPLE 5	3710020-BBC-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Outside Bathrooms east of main office, two single bubbler fountains, upper right fountain
- SAMPLE 2 Outside, Next to girls bathroom and jungle gym, triple bubbler fountain, middle bubbler
- SAMPLE 3 Outside East of room 13, triple bubbler fountain, left bubbler
- SAMPLE 4 Outside bathroom next to the Auditorium in front of Bathrooms, two single bubbler fountains, upper right fountain
- SAMPLE 5 Outside Bathrooms next to Library, three single bubbler fountains, middle fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist