



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/28/17

San Diego Unified School District
Lewis Middle School

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168037	04/21/17	05:33 AM	SAMPLE 1	3710020-AFI-A	< 5	ug/L
W1167284	04/19/17	05:35 AM	SAMPLE 2	3710020-AFI-B	< 5	ug/L
W1167285	04/19/17	05:38 AM	SAMPLE 3	3710020-AFI-C	< 5	ug/L
W1167286	04/19/17	05:41 AM	SAMPLE 4	3710020-AFI-D	< 5	ug/L
W1167287	04/19/17	05:44 AM	SAMPLE 5	3710020-AFI-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Cafeteria single faucet dual sink
- SAMPLE 2 Cafeteria exterior, 2 triple fountains, right triple fountain, left bubbler
- SAMPLE 3 300 BLDG, between custodial #3 door and boys RR, single bubbler fountain next to a dual fountain
- SAMPLE 4 200 BLDG, near room 210 and boys restroom, 2 dual bubbler fountains, right fountain right bubbler
- SAMPLE 5 Boys Gym, near boys locker door and boys restroom, triple bubbler fountain, middle bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist