



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/4/17

San Diego Unified School District
Linda Vista Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168622	04/28/17	06:11 AM	SAMPLE 1	3710020-BCI-A	< 5	ug/L
W1168623	04/28/17	06:25 AM	SAMPLE 2	3710020-BCI-B	< 5	ug/L
W1168624	04/28/17	06:27 AM	SAMPLE 3	3710020-BCI-C	< 5	ug/L
W1168625	04/28/17	06:20 AM	SAMPLE 4	3710020-BCI-D	< 5	ug/L
W1168626	04/28/17	06:15 AM	SAMPLE 5	3710020-BCI-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Kitchen, east interior wall, faucet at sink
SAMPLE 2	RMs 1-13, North exterior wall across from play structure, lower left bubbler
SAMPLE 3	State Preschool, south exterior of RM 7, dual fountain, left bubbler
SAMPLE 4	RMs 14-22, west exterior wall near flagpole, lower left bubbler
SAMPLE 5	cafeteria, south interior wall near kitchen, lower left bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist