



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/23/17

San Diego Unified School District
La Jolla Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1170058	05/12/17	05:58 AM	SAMPLE 1	3710020-BFC-A	< 5	ug/L
W1170059	05/12/17	06:01 AM	SAMPLE 2	3710020-BFC-B	< 5	ug/L
W1170060	05/12/17	06:05 AM	SAMPLE 3	3710020-BFC-C	< 5	ug/L
W1170061	05/12/17	06:08 AM	SAMPLE 4	3710020-BFC-D	< 5	ug/L
W1170062	05/12/17	06:12 AM	SAMPLE 5	3710020-BFC-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Kindergarten Playground, Outside On wall of K-1 classroom near blue table, dual bubbler fountain, right fountain
- SAMPLE 2 Inside K-2 classroom west side Center Island at sink, bubbler at sink
- SAMPLE 3 bldg rooms 1,2, 3, and Conference, Outside East wall next to conference room door, triple bubbler fountain, left bubbler
- SAMPLE 4 bldg rooms 6, 7,10, Outside between boys & girls RRs has checkered tile wall, 3 single bubbler fountains, center fountain
- SAMPLE 5 Auditorium, Inside near double doors, Bubbler drinking fountain on right side of hand washing sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist