



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/12/17

San Diego Unified School District
Marshall Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1169414	05/06/17	08:44 AM	SAMPLE 1	3710020-AJC-A	< 5	ug/L
W1169415	05/06/17	08:41 AM	SAMPLE 2	3710020-AJC-B	< 5	ug/L
W1169416	05/06/17	08:48 AM	SAMPLE 3	3710020-AJC-C	< 5	ug/L
W1169417	05/06/17	08:50 AM	SAMPLE 4	3710020-AJC-D	< 5	ug/L
W1169418	05/06/17	08:54 AM	SAMPLE 5	3710020-AJC-E	< 5	ug/L

<u>Source</u>	<u>Source Description</u>
SAMPLE 1	Kindergarten Building, Room K-1 Interior, Bubbler on faucet
SAMPLE 2	200 Building, Outside of RRs near room 201, dual bubbler fountain, left bubbler
SAMPLE 3	300 building, Outside of RRs near room 309, dual bubbler fountain, right bubbler
SAMPLE 4	Portable RRs near T-1, Middle of upper yard area, triple bubbler fountain, center bubbler
SAMPLE 5	Bungalow Building, South end of lower yard, triple bubbler fountain, center bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist