



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/28/17

San Diego Unified School District
Marvin Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1167335	04/19/17	05:56 AM	SAMPLE 1	3710020-AGA-A	< 5	ug/L
W1167336	04/19/17	06:10 AM	SAMPLE 2	3710020-AGA-B	< 5	ug/L
W1167337	04/19/17	06:07 AM	SAMPLE 3	3710020-AGA-C	< 5	ug/L
W1167338	04/19/17	06:03 AM	SAMPLE 4	3710020-AGA-D	< 5	ug/L
W1167339	04/19/17	05:59 AM	SAMPLE 5	3710020-AGA-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Outside next to lunch court next near kitchen door, 2 dual bubbler fountains, left fixture, right bubbler
- SAMPLE 2 Outside near Room #6 between RR & Supply Closet, 2 single bubbler fountains, right fountain
- SAMPLE 3 Outside near Room #11 between RR's, 2 dual bubbler fountains, right fountain, left bubbler
- SAMPLE 4 Outside bungalow restrooms next to room 19 b, 2 single bubbler fountains, right lower fountain
- SAMPLE 5 at wall outside of kinder classrooms near playground, single bubbler drinking fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist