



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/4/17


San Diego Unified School District
Mason Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168398	04/25/17	06:20 AM	SAMPLE 1	3710020-BAJ-A	< 5	ug/L
W1168399	04/25/17	06:00 AM	SAMPLE 2	3710020-BAJ-B	< 5	ug/L
W1168400	04/25/17	06:05 AM	SAMPLE 3	3710020-BAJ-C	< 5	ug/L
W1168401	04/25/17	06:10 AM	SAMPLE 4	3710020-BAJ-D	< 5	ug/L
W1168402	04/25/17	06:15 AM	SAMPLE 5	3710020-BAJ-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Auditorium, Wall mounted exterior (South of Bldg), between Girls RR & door to Auditorium, facing Gate-Staff Parking Lot, two single bubbler fountains, upper right fountain
- SAMPLE 2 Kitchen (Auditorium), Wall mounted exterior (West of Kitchen, North of Auditorium) facing lunch court, triple bubbler fountain, right bubbler
- SAMPLE 3 500 bldg, Wall mounted exterior (West of Bldg), next to Girls RR, facing 700 Bldg/Portable Classrooms, triple bubbler fountain, left bubbler
- SAMPLE 4 400 bldg, Wall mounted exterior (West of Bldg), next to Girls RR, facing Blacktop/Playground, triple bubbler fountain, middle bubbler
- SAMPLE 5 300 bldg, Wall mounted exterior (South of Bldg), next to Girls RR, facing Goldcoast Dr, two single bubbler fountains, lower right fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist