

Water Quality Chemistry Services
 Lead School Testing
 Report Date: 28-Apr-2017

San Diego Unified School District
San Diego High School

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1167436	4/20/2017	6:24 AM	SAMPLE 1	3710020-AHE-A	< 5	µg/L
W1167437	4/20/2017	6:26 AM	SAMPLE 2	3710020-AHE-B	< 5	µg/L
W1167438	4/20/2017	6:06 AM	SAMPLE 3	3710020-AHE-C	< 5	µg/L
W1167439	4/20/2017	6:18 AM	SAMPLE 4	3710020-AHE-D	< 5	µg/L
W1167440	4/20/2017	6:10 AM	SAMPLE 5	3710020-AHE-E	< 5	µg/L

Source **Source Description**

- SAMPLE 1 100 Building, Inside Culinary Arts Classroom 114 across from range, faucet on single compartment sink
- SAMPLE 2 100 Building, East exterior wall next to Business Center door, two single bubbler fountains, lower right fountain
- SAMPLE 3 200 Building, South exterior wall between boy's locker room and gymnasium doors, triple bubbler fountain, left bubbler
- SAMPLE 4 1100 Building, Inside corridor west wall next to room 1105, two single bubbler fountains, lower right fountain
- SAMPLE 5 900 Building, South exterior wall next to room 901, two single bubbler fountains, lower left fountain

DRL=State Mandated Detection Limit for Reporting (DLR)= 5 µg/L
 Action Level (AL) = 15 µg/L



Doug Campbell, Senior Chemist