



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 5/4/17

San Diego Unified School District
Sandburg Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168393	04/25/17	06:05 AM	SAMPLE 1	3710020-BAI-A	< 5	ug/L
W1168394	04/25/17	06:10 AM	SAMPLE 2	3710020-BAI-B	< 5	ug/L
W1168395	04/25/17	06:15 AM	SAMPLE 3	3710020-BAI-C	< 5	ug/L
W1168396	04/25/17	06:18 AM	SAMPLE 4	3710020-BAI-D	< 5	ug/L
W1168397	04/25/17	06:20 AM	SAMPLE 5	3710020-BAI-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Multipurpose Room, Wall mounted exterior (South of Bldg), between Auditorium Door & Girls' RR, facing Office, two single bubbler fountains, upper right fountain
- SAMPLE 2 Cafeteria & Kitchen, Wall mounted exterior (West of Kitchen, North of Cafeteria), facing lunch court, triple bubbler fountain, right bubbler
- SAMPLE 3 400 bldg, Wall mounted exterior (West of Bldg), facing fence & field, next to Girls RR, triple bubbler fountain, middle bubbler
- SAMPLE 4 Portable Classrooms, Wall mounted exterior (West of Bldg), between Girls & Boys RR, facing Blacktop, two triple bubbler fountains, left fountain, right bubbler
- SAMPLE 5 300 bldg, Wall mounted exterior (South of Bldg), next to Girls rr, facing Kinder Playground, triple bubbler fountain, left bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist