



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/23/17

San Diego Unified School District  
**Vista Grande Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1169380	05/09/17	06:03 AM	SAMPLE 1	3710020-BDJ-A	< 5	ug/L
W1169381	05/09/17	06:05 AM	SAMPLE 2	3710020-BDJ-B	< 5	ug/L
W1169382	05/09/17	06:14 AM	SAMPLE 3	3710020-BDJ-C	< 5	ug/L
W1169383	05/09/17	06:11 AM	SAMPLE 4	3710020-BDJ-D	< 5	ug/L
W1169384	05/09/17	06:08 AM	SAMPLE 5	3710020-BDJ-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1      Main Bldg, Middle hallway behind Health Office and Main Office 1st floor, single bubbler fountain
- SAMPLE 2      Main Bldg, Northeast side of building outside main hallway 1st floor, triple bubbler fountain, middle bubbler
- SAMPLE 3      Main Bldg, Southwest side of building (outside), two single bubbler fountains, lower left bubbler
- SAMPLE 4      Main Bldg, Outside of Room 215 West wall, triple bubbler fountain, right bubbler
- SAMPLE 5      Restroom building, North of room 214, two single bubbler fountains, lower left bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist