



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/12/17

San Diego Unified School District  
**Wilson Middle**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1169404	05/04/17	06:05 AM	SAMPLE 1	3710020-BED-A	< 5	ug/L
W1169405	05/04/17	06:08 AM	SAMPLE 2	3710020-BED-B	< 5	ug/L
W1169406	05/04/17	06:09 AM	SAMPLE 3	3710020-BED-C	< 5	ug/L
W1169407	05/04/17	06:12 AM	SAMPLE 4	3710020-BED-D	< 5	ug/L
W1169408	05/04/17	06:13 AM	SAMPLE 5	3710020-BED-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    500 Building, North face of Interior wall of Kitchen, Faucet on a 2-compartment sink
- SAMPLE 2    500 Building, Northern facing exterior breezeway wall, near lunch shelter, triple bubbler fountain, center bubbler
- SAMPLE 3    400 Building, Exterior west wall, two dual bubbler fountains, left fountain, left bubbler
- SAMPLE 4    Administration Building, Exterior West wall left of stairwell, two single-bubbler fountains, lower left fountain
- SAMPLE 5    300 Building, Exterior east wall, dual bubbler fountain, left bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Tom Burger, Associate Chemist